

Oil Field Environmental Incident Summary

Incident: 20160310142838

Date/Time of Notice: 03/10/2016 14:28

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: STENEHJEM 15X-9H

Field Name: POE

Well File #: 28891

Date Incident: 3/9/2016

Time Incident: 19:50

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 100

Sec: 9

Qtr: SE SW

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine					0	barrels
Other	1.5	Barrels	1.5	Barrels	1.5	barrels

Description of Other Released Contaminant:

Water, gel and sand

Inspected:

Written Report Received: 3/24/2016

Clean Up Concluded: 3/9/2016

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

The spill was contained inside the berm and all fluid was recovered. Clean up was completed by the contractor.

Wastes Disposal Location: Recovered fluid to be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 3/10/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained within the diked area on the well pad. NDIC retains oversight.